

1/44




FIG. 1

202290" TFS500T

2/44




FIG. 2

20250715 15:50:20




FIG. 3

202290" T59500T

4/44




FIG. 4

18

3

5

5

7

20/2290" TFS500F

5/44




FIG. 5

20/2290" FIG. 501

6/44




FIG. 6

202250" T5500T

7/44




FIG. 7




FIG. 8

10055511-062702
20/2290-T55001

8/44




FIG. 9




FIG. 10

1005511.062702

9/44




FIG. 11






FIG. 12

10055511.062703
20/23/2002

10/44



10/055,511-062702

11/44




FIG. 15

20220717 11/44




FIG. 16




FIG. 17




FIG. 18

20/2301163702

13/44




FIG. 19

204290" TFS900T

14/44




FIG. 20

15/44




FIG. 21A




FIG. 21B




FIG. 22

10055511.062702

16/44




FIG. 23

20/2290" T. 59500T

17/44






FIG. 24

204230" 115590T

18/44






FIG. 27




FIG. 28

20/44




FIG. 29

20/44




FIG. 30




FIG. 31

22/44




FIG. 32




FIG. 33

202290" TFS900T

23/44









FIG. 34


202290" TFS500T

24/44



1005511.062703

25/44



26/44




FIG. 40

202290" TFS500T

27/44




FIG. 41

2000015501

28/44





FIG. 42



30/44




FIG. 44

30/44

31/44




FIG. 45




FIG. 46

1005511 062700

32/44




FIG. 47A




FIG. 47B




FIG. 47C

33/44




FIG. 48

202307159001




FIG. 49A




FIG. 49B




FIG. 49C









FIG. 49D

35/44





37/44




FIG. 52

1005511.062702




FIG. 53



40/44




FIG. 55

41/44




FIG. 56

FIG. 57B

FIG. 57B




FIG. 58A




FIG. 58B

43/44




FIG. 59A




FIG. 59B




FIG. 59C

202201155001




FIG. 60A




FIG. 60B